



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAIN BUILDING FORM

CRS # K-2726

1. ADDRESS/LOCATION: 6961 Bay Road, West Side of SR 1 Near Barrett's Chapel
2. FUNCTION(S): historic Dwelling current Dwelling
3. YEAR BUILT: 1865 CIRCA?: ☒ ARCHITECT/BUILDER: \_\_\_\_\_
4. STYLE OR FLOOR PLAN: Vernacular
5. INTEGRITY: original site ☒ moved ☐  
if moved, from where other location's CRS # year  
list major alterations and additions with years (if known) year
  - a. Front block added
  - b. Side porch enclosed
6. CURRENT CONDITION: excellent ☒ good ☐ fair ☐ poor ☐
7. DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
  - a. Overall shape: T-plan Stories: 2.5  
Additions:
  - b. Structural system (if known): Frame
  - c. Foundation: materials: Brick  
basement: full ☒ partial ☐ not visible ☐ no basement ☐
  - d. Exterior walls (original if visible& any subsequent coverings): Vinyl siding
  - e. Roof: shape: Cross gable  
materials: Asphalt Shingle  
cornice: Aluminum  
dormers: n/a  
chimney: location(s): Exterior, north gable end of main block and interior gable end of ell (west)
8. DESCRIPTION OF ELEVATIONS:
  - a. Facade: Direction: E
    - 1) Bays 3
    - 2) Windows 2  
fenestration Irregular  
type 6/6 wood replacement  
trim Aluminum  
shutters Fixed aluminum

## Facade (cont'd)

- 3) Door(s) 1  
     location South end  
     type Six-light wood panel  
     trim Aluminum (including fixed shutters)
- 4) Porch(es) Poured concrete replacement trimmed in brick, hip roof, composite columns

## b. Side: Direction: S

- 1) Bays 5
- 2) Windows 3  
     fenestration Irregular  
     type 1/1 vinyl with diamond mullions  
     trim Aluminum  
     shutters n/a
- 3) Door(s) 1  
     location Center of enclosed porch on ell  
     type Wood replacement  
     trim Aluminum
- 4) Porch(es) Unsheltered replacement brick steps to fully-enclosed porch

## c. Side: Direction: N

- 1) Bays 4
- 2) Windows 2  
     fenestration Irregular  
     type 6/6 sash and 3/3 casement  
     trim Aluminum  
     shutters Fixed
- 3) Door(s) n/a  
     location n/a  
     type n/a  
     trim n/a
- 4) Porch(es) n/a

## d. Rear: Direction: W

- 1) Bays 2
- 2) Windows n/a  
     fenestration n/a  
     type n/a  
     trim n/a  
     shutters n/a
- 3) Door(s) n/a  
     location n/a  
     type n/a  
     trim n/a
- 4) Porch(es) n/a

9. INTERIOR: n/a

10. LANDSCAPING: Long gravel drive to house, gravel drive encircles house, farm fields to north, east and south.

11. OTHER COMMENTS: n/a



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # K-2726

1. ADDRESS/LOCATION: 6961 Bay Road, West Side of SR 1 Near Barrett's Chapel
2. FUNCTION(S):    historic Machine shed                      current Machine shed
3. YEAR BUILT: 1940    CIRCA?: ☒    ARCHITECT/BUILDER: \_\_\_\_\_
4. STYLE/FLOOR PLAN: Vernacular
5. INTEGRITY:            original site ☒                      moved ☐  
    if moved, from where                                      original location's CRS #    year  
\_\_\_\_\_  
    list major alterations and additions with years (if known)                                      year  
    a. \_\_\_\_\_  
    b. \_\_\_\_\_
6. CURRENT CONDITION:                      excellent ☐                      good ☐                      fair ☒                      poor ☐
7. DESCRIPTION:
  - a. Structural system    Pole, frame, and concrete block
  - b. Number of stories    1
  - c. Wall coverings        Corrugated metal, standing seam metal, vinyl siding
  - d. Foundation        None
  - e. Roof  
    structural system    Frame  
    coverings    Standing seam metal  
    openings    n/a
8. DESCRIPTION OF ELEVATIONS:
  - a. Facade: direction: E
    - 1) bays: 5
    - 2) windows: n/a
    - 3) door(s): n/a
    - 4) other: Three open bays, two blind bays

**b. Side: direction: N**

- 1) bays: 2
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: Both bays blind

**c. Side: direction: S**

- 1) bays: 4
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: Three open bays, one blind bay

**d. Rear: direction: W**

- 1) bays: 5
- 2) windows: n/a
- 3) door(s): One corrugated metal hanging door
- 4) other: One open bay, three blind bays

**9. INTERIOR (if accessible):**

a) Floor plan            n/a

b) Partition/walls        n/a

c) Finishes            n/a

d) Furnishings/machinery    n/a



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # K-2726

1. ADDRESS/LOCATION: 6961 Bay Road, West Side of SR 1 Near Barrett's Chapel
2. FUNCTION(S): historic Milkhouse current Storage
3. YEAR BUILT: 1940 CIRCA?: ☒ ARCHITECT/BUILDER: \_\_\_\_\_
4. STYLE/FLOOR PLAN: Vernacular
5. INTEGRITY: original site ☒ moved ☐  
if moved, from where original location's CRS # year
- 
- list major alterations and additions with years (if known)
- |                         | <u>year</u> |
|-------------------------|-------------|
| a. Rebuilt and enlarged | <u>1965</u> |
| b.                      |             |
6. CURRENT CONDITION: excellent ☐ good ☒ fair ☐ poor ☐
7. DESCRIPTION:
- a. Structural system Concrete block
- b. Number of stories 1.5
- c. Wall coverings Vinyl siding in gable ends
- d. Foundation Concrete block on poured concrete slab
- e. Roof  
structural system Frame  
coverings Standing seam metal  
openings n/a
8. DESCRIPTION OF ELEVATIONS:
- a. Facade: direction: E
- 1) bays: 2
- 2) windows: One 2/2 aluminum sash
- 3) door(s): One wood plank hanging door
- 4) other: Aluminum cornice

**b. Side: direction: N**

- 1) bays: 1
- 2) windows: n/a
- 3) door(s): One wood panel hinged pedestrian entrance (off-center)
- 4) other: n/a

**c. Side: direction: S**

- 1) bays: 2
- 2) windows: Two 2/2 sash aluminum
- 3) door(s): n/a
- 4) other: n/a

**d. Rear: direction: W**

- 1) bays: 1
- 2) windows: One 2/2 aluminum sash
- 3) door(s): n/a
- 4) other: n/a

**9. INTERIOR (if accessible):**

a) Floor plan            Open

b) Partition/walls        n/a

c) Finishes            None

d) Furnishings/machinery    n/a





DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SECONDARY BUILDING FORM

CRS # K-2726

1. ADDRESS/LOCATION: 6961 Bay Road, West Side of SR 1 Near Barrett's Chapel

2. FUNCTION(S): historic Wagon shed current Storage

3. YEAR BUILT: 1930 CIRCA?: ☒ ARCHITECT/BUILDER: \_\_\_\_\_

4. STYLE/FLOOR PLAN: Vernacular

5. INTEGRITY: original site ☒ moved ☐  
if moved, from where original location's CRS # year

list major alterations and additions with years (if known) year

a. Bays enclosed

b. \_\_\_\_\_

6. CURRENT CONDITION: excellent ☐ good ☐ fair ☒ poor ☐

7. DESCRIPTION:

a. Structural system Concrete block

b. Number of stories 1

c. Wall coverings Some vinyl siding

d. Foundation Concrete block

e. Roof

structural system Frame

coverings Standing seam metal

openings n/a

8. DESCRIPTION OF ELEVATIONS:

a. Facade: direction: S

1) bays: 7

2) windows: n/a

3) door(s): Six large vinyl hanging doors and one metal-clad single pedestrian door

4) other: n/a

**b. Side: direction: W**

- 1) bays: 1
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: n/a

**c. Side: direction: E**

- 1) bays: 1
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: n/a

**d. Rear: direction: N**

- 1) bays: n/a
- 2) windows: n/a
- 3) door(s): n/a
- 4) other: n/a

**9. INTERIOR (if accessible):**


a) Floor plan            n/a

b) Partition/walls        n/a

c) Finishes            n/a

d) Furnishings/machinery    n/a





DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
MAP FORM


CRS # K-2726

1. ADDRESS/LOCATION: West Side of Route 1, South Murderkill Hundred, Kent County
2. NOT FOR PUBLICATION ☐ reason: \_\_\_\_\_
3. LOCATION MAP:

Indicate position of resource in relation to geographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map )

INDICATE NORTH ON SKETCH




4. SITE PLAN:

CRS #


K-2726

INDICATE NORTH ON PLAN



USE BLACK INK ONLY

CRS-9



DELAWARE STATE HISTORIC PRESERVATION OFFICE  
15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY  
SURVEY UPDATE FORM

CRS # K-2726

1. HISTORIC NAME/FUNCTION: W. Townsend Farm/Farm
2. ADDRESS/LOCATION: 6961 Bay Road, West Side of SR 1 Near Barrett's Chapel
3. CURRENT CONDITION:    excellent ☐    good ☒    fair ☐    poor ☐    demolished ☐
4. INTEGRITY: The house has vinyl siding; the porch deck has been rebuilt; most of the previous outbuildings have been razed and/or replaced.
5. SETTING INTEGRITY: Good; it is still surrounded by agricultural lands.

6. FORMS ADDED (give number of forms completed for each):

#:	Form:	List property types:
1	CRS 2 Main Building Form	Farmhouse
4	CRS 3 Secondary Building Form	Wagonshed, garage, milkhouse, machine shed
0	CRS 4 Archaeological Site Form	
0	CRS 5 Structure (Building-Like) Form	
0	CRS 6 Structure (Land Feature) Form	
0	CRS 7 Object Form	
0	CRS 8 Landscape Elements Form	
0	CRS 9 Map Form	N/A
0	CRS 14 Potential District Form	

7. SURVEYOR INFORMATION:

Surveyor name: Lauren C. Archibald and Christine Tate

Principal Investigator name: Lauren C. Archibald

Principal Investigator signature: \_\_\_\_\_

Organization: A.D. Marble & Company      Date: July 2004



8. OTHER NOTES OR OBSERVATIONS:

CRS# K-2726

This is now known as Holiday Hill Farm.

9. STATE HISTORIC CONTEXT FRAMEWORK (check all appropriate boxes; refer to state management plan(s)):

a) Time period(s)

- ☐ Pre-European Contact
- ☐ Paleo-Indian
- ☐ Archaic
- ☐ Woodland I
- ☐ Woodland II

- ☐ 1600-1750∇ Contact Period (Native American)
- ☐ 1630-1730∇ Exploration and Frontier Settlement
- ☐ 1730-1770∇ Intensified and Durable Occupation
- ☐ 1770-1830∇ Early Industrialization
- ☒ 1830-1880∇ Industrialization and Early Urbanization
- ☐ 1880-1940∇ Urbanization and Early Suburbanization
- ☐ 1940-1960∇ Suburbanization and Early Ex-urbanization

b) Geographical zone

- ☐ Piedmont
- ☒ Upper Peninsula
- ☐ Lower Peninsula/Cypress Swamp
- ☐ Coastal
- ☐ Urban (City of Wilmington)

c) Historic period theme(s)

- |   |  |
|---|--|
| <input checked="" type="checkbox"/> Agriculture | <input type="checkbox"/> Transportation and Communication              |
| <input type="checkbox"/> Forestry               | <input type="checkbox"/> Settlement Patterns and Demographic Changes   |
| <input type="checkbox"/> Trapping/Hunting       | <input type="checkbox"/> Architecture, Engineering and Decorative Arts |
| <input type="checkbox"/> Mining/Quarrying       | <input type="checkbox"/> Government                                    |
| <input type="checkbox"/> Fishing/Oystering      | <input type="checkbox"/> Religion                                      |
| <input type="checkbox"/> Manufacturing          | <input type="checkbox"/> Education                                     |
| <input type="checkbox"/> Retailing/Wholesaling  | <input type="checkbox"/> Community Organizations                       |
| <input type="checkbox"/> Finance                | <input type="checkbox"/> Occupational Organizations                    |
| <input type="checkbox"/> Professional Services  | <input type="checkbox"/> Major Families, Individuals and Events        |

## **CRS #K-2726**

### **Townsend Farm**

**Dwelling.** This cross-gable vernacular frame farmhouse is in excellent condition but has been remodeled extensively. The main block of the dwelling is a two-and-one-half-story I-house on a brick foundation with an exterior brick chimney on the northern elevation. It has a three-bay façade with a full-length, hipped-roof open porch facing east (toward SR 1), with the main entrance at its southern end. The porch deck has been replaced with concrete, the steps have been replaced with brick, and the columns and gingerbread trim have been replaced with modern composites. What is now the ell of the dwelling (though the plan has been all but entirely filled in with the enclosure of a single-story, shed-roofed porch on the southern elevation) was the original farmhouse and is at least several decades older than the larger addition. This portion, as one-and-one-half-story frame dwelling, appears to have originally faced south. Though there is still a parged brick interior chimney at its western end, the homeowner (whose family has lived in the house for nearly a century) indicated that it was no longer functioning and that the summer kitchen, with which it shared a wall, was demolished 20 or more years ago. It is not clear when the "front" porch of the original house was enclosed but such alterations are typical of the second half of the twentieth century. The entire structure has been re-clad in vinyl siding and has replacement windows, aluminum trim, fixed aluminum shutters, and an asphalt shingle roof. Only the silhouette of a vernacular farmhouse remains.

**Garage.** Behind the house and to its southwest sits a gable-front two-car garage built ca. 1970. It is a concrete block structure on a poured concrete slab with an asphalt shingle roof, and aluminum siding in the gable ends. There are two overhead garage doors on the façade (northern elevation), two double-hung sash windows on the western elevation, and one double-hung sash window and a pedestrian entrance on the eastern elevation. On the southern elevation is an exterior concrete block chimney.

**Milkhouse.** Although this structure is still referred to as a milkhouse, this building is now used as a storage shed. This shed is a small, rectangular concrete block structure on a poured concrete slab with an asphalt shingle roof and aluminum siding in the gable ends. The homeowner indicated that it had been completely rebuilt and enlarged in the second half of the twentieth century.

**Wagon Shed.** This long, side-gable, concrete-block structure with a standing seam metal roof appears to date from ca. 1930. It is partially sheathed in vinyl siding (in the gable ends, more than half of the northern elevation, and some of the façade). Six of the open bays on the façade (southern elevation) have been closed off with modern, hanging vinyl doors, and the westernmost bay has been sealed with siding and is accessible via a modern aluminum pedestrian door.

**Machine Shed Complex.** This is an L-shaped conglomeration of three structures, all with open facades and all attached to each other but facing three different directions. The largest section is a metal-clad pole shed facing the farm yard to the east, though it has one hanging metal door on the rear elevation. Attached to its south wall is the tallest and narrowest structure, also sheathed in metal, but facing the farm fields to the west. Attached to its eastern wall is a shed that faces



more fields to the south. The western wall of this section is concrete block and its eastern elevation is frame sheathed in vinyl siding. The homeowner claimed that some part of the largest building used pole supports from an old barn and one or two of its supports were trees *in situ*.

**Historical Background.** A property in this location is shown on the 1868 Beers Atlas as "W. Townsend"; however, courthouse deed records could not be traced back to the nineteenth century. Courthouse records do indicate that in December 1911, this property, which did belong to William Townsend, was conveyed to Jester A. Gray through Orphans Court proceedings (KCDB R2: 300). On July 20, 1916, Jester A. and Sallie B. Gray sold the property containing 85.0 acres along with the "...farm, tract, piece or parcel of land...and all singular buildings and improvements" to Liston H. Webb for \$8,566.88 (KCDB A11: 177). On October 31, 1952, Liston H. Webb sold the property containing 85.0 acres along with "...all that farm, tract, and premises situated" to Helen Mae and Samuel Webb for \$10,000 (KCDB V19: 154). On May 19, 1994 Samuel Webb passed away, and on November 10, 1994, Helen Mae Webb conveyed the property Timothy and Lesley Valeski (KCDB D106: 276). On July 17, 1997, Timothy and Lesley Valeski conveyed the property containing 73.6 acres to Helen Mae Webb (KCDB D224: 60). The lands immediately surrounding the house are still being farmed today, but not by the current owner. The W. Townsend Property (CRS # K-2726) may have been a tenant farm historically based, in part, on research conducted by the University of Delaware (Siders et al. 1991; Appendix A).

**Significance Requirements for Agricultural Property Types.** To be eligible under Criterion A, an agricultural property must have originally, or through much of its history, been associated with and be reflective of a trend or pattern in agriculture, and include both the land and the buildings where these agricultural trends took place. Trends may include agricultural practices confined to a specific period, or those that reflect substantial change and adaptation over time. To be eligible under Criterion B in the area of agriculture, a property must include buildings or structures that represent the contribution of an individual who has played a role in the historic agricultural development and/or prosperity of the area. To be eligible under Criterion C in the area of architecture, a farm must include a building or structure that embodies the distinctive characteristics of a type, period, or method of construction. For example, a farmhouse may represent the characteristics or construction methods of an architectural style or type of vernacular architecture popular Kent County, the region, or Delaware in a given period.

In order to be seen as a significant example of a farm, resources must possess land reflecting agricultural use, a house, a barn, and other domestic and/or agricultural outbuildings and structures (exclusive of the main house/barn). It should also include some vegetation associated with the farm, including kitchen gardens, cultivated fields, woodlots, and orchards. Other characteristics may consist of a circulation network connecting the parts of the farm, including farm lanes and paths. In order to be seen as significant as an example of a farm building, a resource should be a unique or rare example of a barn, housing, outbuilding type, or landscape feature. It may also be a well-preserved example of a barn, housing, or outbuilding type that retains exceptional integrity of materials and design. A rural historic landscape should be evaluated as one or a number of historic districts. These historic districts may connect or overlap and some of the districts may extend into adjacent areas.



**Evaluation.** Though property is still surrounded by farm fields, all of the extant outbuildings have been added, rebuilt with substantial modifications, or altered beyond recognition in recent years. They retain no appreciable integrity for any period before the last quarter of the twentieth century. The Townsend Farm (CRS #K-2726) is recommended not eligible for listing in the National Register of Historic Places because it does not meet the eligibility criteria established by the National Park Service (NPS 1997), nor does it meet the requirements as a significant agricultural property as developed in this study (see section above under "Significance Requirements for Agricultural Property Types"). It does not possess all of the necessary qualities necessary to be considered a significant farm; similarly, it lacks the salient characteristics for consideration both as a significant individual farm building and as a significant individual dwelling. The resource is an example of a highly-altered, nineteenth-century residence within the SR 1 Interchange study area. Property-specific research and documentary research of the area in general did not reveal any associations between this property and significant events or trends. The property is recommended not eligible for listing in the National Register under Criterion A for this reason. Likewise, research did not reveal any associations with significant individuals; therefore, the property is recommended not eligible for listing under Criterion B. The Townsend Farm does not display the distinctive characteristics of a type, style, or method of construction, nor does it represent the work of a master or possess high artistic value; therefore, it is recommended not eligible under Criterion C. Although this farmstead has lost its associated historic barn(s) and most of its historic outbuildings, there could be historic archaeological potential at this property, and this could potentially yield information about agricultural tenancy in central Delaware. Archaeological investigations have not yet been conducted on this property; therefore, the resource's eligibility under Criterion D (potential to yield information important to history or prehistory) cannot be assessed at this time.

## Bibliography

Kent County Recorder of Deeds (KCDB)

Kent County Deed Books, Kent County Courthouse, Dover, Delaware.

Kent County Tax Assessor's Office

Kent County Courthouse, Dover, Delaware.

National Park Service (NPS)

1997 *National Register Bulletin 15: How to Apply the National Register Criteria for Evaluation*. U.S. Government Printing Office, Washington, D.C.

Siders, Rebecca J., Benard L. Herman, David L. Ames et al.


1991 *Agricultural Tenancy in Central Delaware 1770-1900+/-*. Center for Historic Architecture and Engineering, College of Urban Affairs and Public Policy, University of Delaware, Newark, Delaware.

Helen Webb, property owner, personal communication, July 26, 2004.



# CULTURAL RESOURCE SURVEY LOCUS IDENTIFICATION FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



FORM CRS-2

FOR OFFICE USE ONLY

CRS # 4-2726  
Quad Fredonia  
SPO map # 12-13-18  
Hundred S. Mendenhall  
DOCUMENT 20-06/78/04/7


1. NAME OF LOCUS: W. TOWNSEND (DELL'S)
2. STREET LOCATION: Highway 113
3. OWNER'S NAME: \_\_\_\_\_ TEL. # \_\_\_\_\_  
ADDRESS: \_\_\_\_\_
4. TYPE OF LOCUS: a) structure ☒ b) district \_\_\_\_\_ c) archaeological site \_\_\_\_\_  
d) other \_\_\_\_\_
5. SURROUNDINGS OF LOCUS: (check more than one if necessary)  
a) fallow field ☒ b) cultivated field ☒ c) woodland \_\_\_\_\_  
d) scattered buildings \_\_\_\_\_ e) densely built up \_\_\_\_\_ f) other \_\_\_\_\_
6. THREATS TO LOCUS: (check more than one if necessary)  
a) none known ☒ b) zoning \_\_\_\_\_ c) roads \_\_\_\_\_ d) developers \_\_\_\_\_  
e) deterioration \_\_\_\_\_ f) other \_\_\_\_\_
7. REPRESENTATION ON OTHER SURVEYS:  
TITLE: \_\_\_\_\_ # \_\_\_\_\_  
TITLE: \_\_\_\_\_ # \_\_\_\_\_  
TITLE: \_\_\_\_\_ # \_\_\_\_\_
8. YOUR NAME: Gordon Sands TEL. # \_\_\_\_\_  
YOUR ADDRESS: \_\_\_\_\_  
ORGANIZATION (if any) S.A.N.P. DATE: 6-24-88

USE BLACK INK ONLY



## 3. SKETCH MAP

Please indicate position of locus in relation to geographical landmarks such as streams and roads.



INDICATE NORTH ON SKETCH

USE BLACK INK ONLY

## 9. COMMENTS:

Consider the following:

- a) relationship to setting
- b) associated traditions or stories
- c) noteworthy features
- d) comparison with others in area

- a) 3maga
- b) sheds
- c) Barns
- d) corn crib
- e) shed coops
- f) Silo



# CULTURAL RESOURCE SURVEY STRUCTURAL DATA FORM

DELAWARE BUREAU OF  
ARCHAEOLOGY AND HISTORIC  
PRESERVATION  
HALL OF RECORDS  
DOVER, DELAWARE 19901  
(302) 678-5314



Form CRS-1  
FOR OFFICE USE ONLY

CRS # K-2726  
Quad Fredonia  
SPO map # 12-13-18  
Hundred 2 MURDERKILL  
DOCUMENT 20-06/78/08/14

1. ADDRESS OF STRUCTURE : RTE. 113 NEAR RD. 372

2. DESCRIBE THE STRUCTURE AS COMPLETELY AS POSSIBLE:

a) Overall shape

stories 2

bays 3

wings 1 1/2

REAR ELL, STUCCOED BRICK

b) Structural system FOUND., UPPER WINDOWS 3/3 SASH, INT. END  
BRICK CHIMNEY, 1 1/2 SM.  
SASH WINDOW PIERCES  
GABLE END

c) Foundation materials BRICK (WHITEWASHED)  
basement BULKHEAD ENTR.

d) Exterior walls materials ASBESTOS SHINGLE  
color(s) GREY


e) Roof shape; materials GABLE  
cornice BOX W/ PARTIAL RETURNS (NOW COVERED W/ ALUMINUM SIDING)  
dormers —  
chimney location(s) EXTERIOR END BRICK ON MAIN BLOCK (RECENT)

f) Windows spacing 3 BAY, SIDE DOOR, SYMMETRICAL  
type 1/6 SASH  
trim PLAIN BOARD SURROUND W/ SILL  
shutters NON-FUNCTIONAL ALUMINUM  
2 SM. 2 1/2 SASH  
WINDOWS PIERCE  
GABLE ENDS

g) Door spacing 3 BAY, SIDE DOOR  
type (REPLACED W/ MODERN DOOR)  
trim ALUM. SHUTTERS

h) Porches location(s) FACADE  
materials BRICK AND CONCRETE PAD FOUNDATION (RECENT), HIPPED ROOF  
supports 3 ALUMINUM PULVED DORIC COLUMNS  
trim —

i) Interior details (if accessible) REAR ELL - CEMENT BLOCK  
FOUNDATION, SHED DOOF, ENCLOSED  
PORCH, ALUM. SASH WINDOWS



USE BLACK INK ONLY



PHOTOGRAPHIC INVENTORY

BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION

Document 20-06/79/01/11


CRS Number K-2726 Date 8-80 Contact Sheet # C-1259

Description 2) barn 3) Lside 4) Lside 5) outbuildings

6) back 7) outbuilding

Location (if other than Bureau collection) \_\_\_\_\_

Attach contact print



PHOTOGRAPHIC INVENTORY

BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION

Document 20-06/79/01/11

CRS Number K-2726 Date 8-80 Contact Sheet # C-1258

Description 20) 3/4 front & R side -) house & outbuildings

Location (if other than Bureau collection) \_\_\_\_\_

Attach contact print





PHOTOGRAPHIC INVENTORY

BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION

Document 20-06/79/01/11

CRS Number K-2726 Date 8-80 Contact Sheet # C-1258

Description 20) 3/4 front & R side -) house & outbuildings

Location (if other than Bureau collection) \_\_\_\_\_

Attach contact print



PHOTOGRAPHIC INVENTORY

BUREAU OF ARCHAEOLOGY AND HISTORIC PRESERVATION

Document 20-06/79/01/11

CRS Number K-2726 Date 8-80 Contact Sheet # C-1259

Description 2) barn 3) L side 4) L side 5) outbuildings  
6) back 7) outbuilding

Location (if other than Bureau collection) \_\_\_\_\_

Attach contact print

